




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2385</b>																									
<b>Priority :</b>	High																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9819990297																								
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-12-2020 09:55:07																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Bhoomi Ganga Enclave A Wing	Customer's Mobile :	9819990297	Name :	Vipul Bhai																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-12-2020 12:00:00		Type :	Non-Comprehensive																					
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	Multi apartment system issue																								
<b>Technician Comment :</b>	lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-12-2020 12:50:47</td><td>YogeshDesai</td><td>Completed</td><td>lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats</td><td></td></tr><tr><td>08-12-2020 09:56:15</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>08-12-2020 09:55:07</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-12-2020 12:50:47	YogeshDesai	Completed	lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats		08-12-2020 09:56:15	YogeshDesai	New		-	08-12-2020 09:55:07	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
08-12-2020 12:50:47	YogeshDesai	Completed	lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats																						
08-12-2020 09:56:15	YogeshDesai	New		-																					
08-12-2020 09:55:07	YogeshDesai	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-12-2020 03:31:14</td><td>Parshva Shah</td><td></td></tr><tr><td>03-12-2020 10:55:23</td><td></td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	08-12-2020 03:31:14	Parshva Shah		03-12-2020 10:55:23													
Date Time	Technician Name	Remark																							
08-12-2020 03:31:14	Parshva Shah																								
03-12-2020 10:55:23																									