

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4906																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9819990297																																		
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																															
Ticket Type :	Complain	Date & Time :	01-03-2022 09:51:09																																
Vendor Details :																																			
Company Name/Client Name :	Bhoomi Ganga Enclave A Wing	Customer's Mobile :	9819990297	Name :	Vipul Bhai																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	31-12-2020 12:00:00		Type :	Non-Comprehensive																															
Product Name :	VDP																																		
Complain :	flat no 504 cannot view lobby camera																																		
Technician Comment :	504 lobby video issue resolved 4 th floor side video distributor change and old fulty distributor take to office																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	504 lobby video issue resolved 4 th floor side video distributor change and old fulty distributor take to office																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-03-2022 12:46:40</td><td>Siddhesh Chavan</td><td>Completed</td><td>504 lobby video issue resolved 4 th floor side video distributor change and old fulty distributor take to office</td><td></td></tr><tr><td>02-03-2022 10:38:54</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>01-03-2022 11:33:35</td><td>Siddhesh Chavan</td><td>Awaiting Spares</td><td>4 th floor vdeo distribter faulty data not transferin check by 6 floor distributor swap so need to changed this .</td><td></td></tr><tr><td>01-03-2022 09:51:22</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>01-03-2022 09:51:09</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-03-2022 12:46:40	Siddhesh Chavan	Completed	504 lobby video issue resolved 4 th floor side video distributor change and old fulty distributor take to office		02-03-2022 10:38:54	Siddhesh Chavan	New		-	01-03-2022 11:33:35	Siddhesh Chavan	Awaiting Spares	4 th floor vdeo distribter faulty data not transferin check by 6 floor distributor swap so need to changed this .		01-03-2022 09:51:22	Siddhesh Chavan	New		-	01-03-2022 09:51:09	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																															
02-03-2022 12:46:40	Siddhesh Chavan	Completed	504 lobby video issue resolved 4 th floor side video distributor change and old fulty distributor take to office																																
02-03-2022 10:38:54	Siddhesh Chavan	New		-																															
01-03-2022 11:33:35	Siddhesh Chavan	Awaiting Spares	4 th floor vdeo distribter faulty data not transferin check by 6 floor distributor swap so need to changed this .																																
01-03-2022 09:51:22	Siddhesh Chavan	New		-																															
01-03-2022 09:51:09	Siddhesh Chavan	New		-																															

Previous Complain History :			
	Date Time	Technician Name	Remark
	03-03-2022 10:14:52	Siddhesh Chavan	A wing 505 vdp video issue resolved video distributor side cable reconnect and video issue resolved
	02-03-2022 11:37:40	Siddhesh Chavan	705 vdp working ok