Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \mathbf{W}: \text{www.vallabhenterprises.com} \\ \mathbf{E}: \text{vallabhsecure@yahoo.co.in}$

Service Status Details : VE6349								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob.	9819990297							
Technician Name :	Yogesh Desai		Technician Mobile :		8080922963			
Ticket Type :	Complain	Date & Time:	10-09-2022 11:13:54					
Vendor Details :								
Company Name/Client Name :	Bhoomi Ganga Enclave A Wing	Customer's Mobile :	9819990297		Name :	Vipul Bhai		
Address:								
Mumbai,,,,Maharashtra								
AMC Details :	-				_			
Expiry Date :	31-12-2020 12:00:	00	Type:		Non-Comprehensive			
Product Name:	CCTV							
Complain:	need to check cable							
Technician Comment :	cctv camera survey done fir unarmoured cameras cable done alk together 11 camera are there one camera of 6th floor removed or not in place 16 channel Hikvision dvr. survey of camera completed.							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	cctv camera survey done fir unarmoured cameras cable done alk together 11 camera are there one camera of 6th floor removed or not in place 16 channel Hikvision dvr. survey of camera completed.							
Status History:	Date Time	Technician Name	Status	Remark		Sign		
	10-09-2022 11:23:03	YogeshDesai	Completed	cctv camera survey done fir unarmoured cameras cable done alk together 11 camera are there one camera of 6th floor removed or not in place 16 channel Hikvision dvr. survey of camera completed.		RdhW		
	10-09-2022 11:14:06	YogeshDesai	New			-		
	10-09-2022 11:13:54	YogeshDesai	New			-		
Previous	Date Time	Technician Name	Remark					
Complain History :	19-09-2022 02:53:06	Sonu Kumar	2 camera issue resolved working ok and 4 BNC used and 6th floor camera missing					
	13-09-2022 05:17:14	4 YogeshDesai	camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.					