




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6364																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9819990297																													
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																										
Ticket Type :	Complain	Date & Time :	13-09-2022 04:13:49																											
Vendor Details :																														
Company Name/Client Name :	Bhoomi Ganga Enclave A Wing	Customer's Mobile :	9819990297	Name :	Vipul Bhai																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	31-12-2020 12:00:00		Type :	Non-Comprehensive																										
Product Name :	Access																													
Complain :	Biometric door access issue																													
Technician Comment :	Biometric issue of access has been sloved power supply was faulty new power has been installed biometric working ok.door can now be open .																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Biometric issue of access has been sloved power supply was faulty new power has been installed biometric working ok.door can now be open .																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-09-2022 01:09:58</td><td>YogeshDesai</td><td>Cancelled</td><td></td><td>-</td></tr><tr><td>13-09-2022 05:33:35</td><td>YogeshDesai</td><td>Completed</td><td>Biometric issue of access has been sloved power supply was faulty new power has been installed biometric working ok.door can now be open .</td><td></td></tr><tr><td>13-09-2022 04:14:04</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>13-09-2022 04:13:49</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-09-2022 01:09:58	YogeshDesai	Cancelled		-	13-09-2022 05:33:35	YogeshDesai	Completed	Biometric issue of access has been sloved power supply was faulty new power has been installed biometric working ok.door can now be open .		13-09-2022 04:14:04	YogeshDesai	New		-	13-09-2022 04:13:49	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																										
24-09-2022 01:09:58	YogeshDesai	Cancelled		-																										
13-09-2022 05:33:35	YogeshDesai	Completed	Biometric issue of access has been sloved power supply was faulty new power has been installed biometric working ok.door can now be open .																											
13-09-2022 04:14:04	YogeshDesai	New		-																										
13-09-2022 04:13:49	YogeshDesai	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-09-2022 02:53:06</td><td>Sonu Kumar</td><td>2 camera issue resolved working ok and 4 BNC used and 6th floor camera missing</td></tr><tr><td>13-09-2022 05:17:14</td><td>YogeshDesai</td><td>camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-09-2022 02:53:06	Sonu Kumar	2 camera issue resolved working ok and 4 BNC used and 6th floor camera missing	13-09-2022 05:17:14	YogeshDesai	camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.																
Date Time	Technician Name	Remark																												
19-09-2022 02:53:06	Sonu Kumar	2 camera issue resolved working ok and 4 BNC used and 6th floor camera missing																												
13-09-2022 05:17:14	YogeshDesai	camera old pcb has been changed and new pcb for camera has been replaced there is no continuously ringing in vdp all working ok.																												