Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE6521 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9819990297 **No. :** Technician Siddhesh Chavan **Technician Mobile** 8080922985 Name : Complain 07-10-2022 10:22:53 **Ticket Type :** Date & Time : **Vendor Details :** Bhoomi Ganga Customer's Mobile 9819990297 Name : Vipul Bhai Company Name/Client Enclave A Wing Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-12-2020 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** VDP **Complain**: 701 6th floor distributor to flat vdp side cat 6 cable issue need to change cable 701 lobby video issue resolved and vdp working ok and finger add to biomatric Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 701 lobby video issue resolved and vdp working ok and finger add to biomatric **Status History :** Date Time **Technician Name** Status Remark Sign 20-10-2022 04:23:17 Siddhesh Chavan Closed 07-10-2022 05:19:26 Siddhesh Chavan Completed 701 lobby video issue resolved and vdp working ok and finger add to biomatric 07-10-2022 02:58:38 Siddhesh Chavan New 07-10-2022 02:23:56 Siddhesh Chavan Work Pending vdp cabling done with casing patti VQVL 07-10-2022 10:23:26 Siddhesh Chavan New 07-10-2022 10:22:53 Siddhesh Chavan New **Previous Date Time Technician Name** Remark Complain 17-10-2022 05:20:12 Siddhesh Chavan 702 vdp video issue resolved and lobby video working ok **History** : 15-10-2022 01:11:25 Siddhesh Chavan 301 lobby video view issue resolved and 2 nd and 3 rd floor staircase side video disubtr change and 2 nd and 3 floor lobby video issue resolved