

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9741																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9969112258																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	05-10-2023 05:45:00																	
Vendor Details :																				
Company Name/Client Name :	Yadavji Khar Site	Customer's Mobile :	9969112258	Name :	Yadav Ji															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Khar Site 1 camera issue																			
Technician Comment :	Camera nmbr 2 gate nmbr 2 mixer machine side cable break power not coming camera end So check from gate power coming need to changed cable .																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Camera nmbr 2 gate nmbr 2 mixer machine side cable break power not coming camera end So check from gate power coming need to changed cable .																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-10-2023 12:27:44</td><td>Atique Salmani</td><td>Client Side</td><td>Camera nmbr 2 gate nmbr 2 mixer machine side cable break power not coming camera end So check from gate power coming need to changed cable .</td><td></td></tr><tr><td>06-10-2023 10:03:38</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-10-2023 12:27:44	Atique Salmani	Client Side	Camera nmbr 2 gate nmbr 2 mixer machine side cable break power not coming camera end So check from gate power coming need to changed cable .		06-10-2023 10:03:38	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
06-10-2023 12:27:44	Atique Salmani	Client Side	Camera nmbr 2 gate nmbr 2 mixer machine side cable break power not coming camera end So check from gate power coming need to changed cable .																	
06-10-2023 10:03:38	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-12-2023 02:21:43</td><td>Atique Salmani</td><td>Camera need to shift also cabling need to do becz cable break</td></tr><tr><td>20-10-2023 05:32:14</td><td>Ishwar Meena</td><td>3 bullet canera instoll and 100 meter cable and 4 chn dvr 2tv hard disk 2u rack smps</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-12-2023 02:21:43	Atique Salmani	Camera need to shift also cabling need to do becz cable break	20-10-2023 05:32:14	Ishwar Meena	3 bullet canera instoll and 100 meter cable and 4 chn dvr 2tv hard disk 2u rack smps						
Date Time	Technician Name	Remark																		
14-12-2023 02:21:43	Atique Salmani	Camera need to shift also cabling need to do becz cable break																		
20-10-2023 05:32:14	Ishwar Meena	3 bullet canera instoll and 100 meter cable and 4 chn dvr 2tv hard disk 2u rack smps																		