

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9750																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9969112258																																		
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153																															
Ticket Type :	Complain	Date & Time :	06-10-2023 02:51:21																																
Vendor Details :																																			
Company Name/Client Name :	Lalita Electrical	Customer's Mobile :	9969112258	Name :	Yadav Ji																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	Site: Golpa Mata mandir - 2 cameras blur issue and 1 camera off issue																																		
Technician Comment :	1 camera disturbance issue resolve working done. Dvr side BNC connector change.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	1 camera disturbance issue resolve working done. Dvr side BNC connector change.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-10-2023 03:46:25</td><td>PravinJagade</td><td>Completed</td><td>1 camera disturbance issue resolve working done. Dvr side BNC connector change.</td><td></td></tr><tr><td>11-10-2023 03:44:32</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr><tr><td>11-10-2023 01:53:17</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr><tr><td>07-10-2023 12:00:22</td><td>PravinJagade</td><td>Work Pending</td><td>1camera line issue</td><td></td></tr><tr><td>06-10-2023 10:36:14</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-10-2023 03:46:25	PravinJagade	Completed	1 camera disturbance issue resolve working done. Dvr side BNC connector change.		11-10-2023 03:44:32	PravinJagade	New		-	11-10-2023 01:53:17	PravinJagade	New		-	07-10-2023 12:00:22	PravinJagade	Work Pending	1camera line issue		06-10-2023 10:36:14	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																															
11-10-2023 03:46:25	PravinJagade	Completed	1 camera disturbance issue resolve working done. Dvr side BNC connector change.																																
11-10-2023 03:44:32	PravinJagade	New		-																															
11-10-2023 01:53:17	PravinJagade	New		-																															
07-10-2023 12:00:22	PravinJagade	Work Pending	1camera line issue																																
06-10-2023 10:36:14	PravinJagade	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>05-10-2023 05:45:00</td><td>Atique Salmani</td><td>Camera nmbr 2 gate nmbr 2 mixer machine side cable break power not coming camera end So check from gate power coming need to changed cable .</td></tr><tr><td>22-09-2023 10:50:32</td><td>ChandanYadav</td><td>Camera lineing ieesu solve.</td></tr></tbody></table>					Date Time	Technician Name	Remark	05-10-2023 05:45:00	Atique Salmani	Camera nmbr 2 gate nmbr 2 mixer machine side cable break power not coming camera end So check from gate power coming need to changed cable .	22-09-2023 10:50:32	ChandanYadav	Camera lineing ieesu solve.																					
Date Time	Technician Name	Remark																																	
05-10-2023 05:45:00	Atique Salmani	Camera nmbr 2 gate nmbr 2 mixer machine side cable break power not coming camera end So check from gate power coming need to changed cable .																																	
22-09-2023 10:50:32	ChandanYadav	Camera lineing ieesu solve.																																	