




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5933																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8080488068																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	12-07-2022 10:52:01																						
Vendor Details :																									
Company Name/Client Name :	Rudra Securities	Customer's Mobile :	8080488068	Name :	Yash Doshi																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	site -shankar gully surana hospital -intercom																								
Technician Comment :	main gate security cabin line ok instrument issue 104 line off bcz cable cut out side and cable rejoined and ok working done intercom system check sky link 64 port cron junction box very poor fist floor junction box to all floor cable dropping with direct joined																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	main gate security cabin line ok instrument issue 104 line off bcz cable cut out side and cable rejoined and ok working done intercom system check sky link 64 port cron junction box very poor fist floor junction box to all floor cable dropping with direct joined																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-07-2022 11:41:58</td><td>Ravi Rajbhar</td><td>Completed</td><td>main gate security cabin line ok instrument issue 104 line off bcz cable cut out side and cable rejoined and ok working done intercom system check sky link 64 port cron junction box very poor fist floor junction box to all floor cable dropping with direct joined</td><td></td></tr><tr><td>12-07-2022 10:52:16</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>12-07-2022 10:52:01</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-07-2022 11:41:58	Ravi Rajbhar	Completed	main gate security cabin line ok instrument issue 104 line off bcz cable cut out side and cable rejoined and ok working done intercom system check sky link 64 port cron junction box very poor fist floor junction box to all floor cable dropping with direct joined		12-07-2022 10:52:16	Ravi Rajbhar	New		-	12-07-2022 10:52:01	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
12-07-2022 11:41:58	Ravi Rajbhar	Completed	main gate security cabin line ok instrument issue 104 line off bcz cable cut out side and cable rejoined and ok working done intercom system check sky link 64 port cron junction box very poor fist floor junction box to all floor cable dropping with direct joined																						
12-07-2022 10:52:16	Ravi Rajbhar	New		-																					
12-07-2022 10:52:01	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-06-2022 01:05:06</td><td>Atique Salmani</td><td></td></tr><tr><td>08-06-2022 11:12:09</td><td>YogeshDesai</td><td>Two , three camera disturbance issue solved all camera working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-06-2022 01:05:06	Atique Salmani		08-06-2022 11:12:09	YogeshDesai	Two , three camera disturbance issue solved all camera working ok.											
Date Time	Technician Name	Remark																							
10-06-2022 01:05:06	Atique Salmani																								
08-06-2022 11:12:09	YogeshDesai	Two , three camera disturbance issue solved all camera working ok.																							

