

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15239																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9022376306																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	11-07-2025 02:51:55																	
Vendor Details :																				
Company Name/Client Name :	Rudra Heights	Customer's Mobile :	9022376306	Name :	Yash Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	VDP and access issue																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Rudra Hights lobby access start and 1801 video door phone stand lobby and out door unit																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-07-2025 03:21:06</td><td>Ravi Rajbhar</td><td>Completed</td><td></td><td>-</td></tr><tr><td>11-07-2025 03:14:32</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-07-2025 03:21:06	Ravi Rajbhar	Completed		-	11-07-2025 03:14:32	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
11-07-2025 03:21:06	Ravi Rajbhar	Completed		-																
11-07-2025 03:14:32	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-05-2025 11:04:05</td><td>Atique Salmani</td><td>1st lift camera installed and in duct transmeter adaptor installation done but camera not working becz cable faulty need to new cabling from ground duct to lift pit 25.28 metr approx so it's painding</td></tr><tr><td>20-05-2025 03:57:38</td><td>Ravi Rajbhar</td><td>Dvr to poe cable cut so used new d link 1 metr pachcode and 1 lif 1 bullet camera issue resolved one dome camera collect</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-05-2025 11:04:05	Atique Salmani	1st lift camera installed and in duct transmeter adaptor installation done but camera not working becz cable faulty need to new cabling from ground duct to lift pit 25.28 metr approx so it's painding	20-05-2025 03:57:38	Ravi Rajbhar	Dvr to poe cable cut so used new d link 1 metr pachcode and 1 lif 1 bullet camera issue resolved one dome camera collect						
Date Time	Technician Name	Remark																		
28-05-2025 11:04:05	Atique Salmani	1st lift camera installed and in duct transmeter adaptor installation done but camera not working becz cable faulty need to new cabling from ground duct to lift pit 25.28 metr approx so it's painding																		
20-05-2025 03:57:38	Ravi Rajbhar	Dvr to poe cable cut so used new d link 1 metr pachcode and 1 lif 1 bullet camera issue resolved one dome camera collect																		