Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: valiabilsecure@yaiioo.co.iii							
Service Status Details : VE4778							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9022376306						
Technician Name :	Ravi Rajbhar		Technici	Technician Mobile:		8080922965	
Ticket Type :	New Installation	Date & Time:	14-02-2022 11:46:42				
Vendor Details :							
Company Name/Client Name :	Rudra Heights	Customer's Mobile	9022376306		Name :	Yash Sir	
Address:							
Mumbai , , , , Mal	narashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:	Type:			
Product Name:	CCTV						
Complain:	new cctv installation with cabling						
Technician Comment :	total 5 ccamera install 4ch DVR install SRS building 16 Ch DVR install rudra building both DVR recording going on in DVR both DVR password admin@123 both DVR Fram rate bit rate 18 /1024 one camera work pending lobby						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	total 5 ccamera install 4ch DVR install SRS building 16 Ch DVR install rudra building both DVR recording going on in DVR both DVR password admin@123 both DVR Fram rate bit rate 18 /1024 one camera work pending lobby						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	15-02-2022 04:18:02	Ravi Rajbhar	Completed	total 5 ccamera install 4ch DVR install SRS building 16 Ch DVR install rudra building both DVR recording going on in DVR both DVR password admin@123 both DVR Fram rate bit rate 18 /1024 one camera work pending lobby		Grant	
	15-02-2022 03:28:28	Ravi Rajbhar	New			-	
	15-02-2022 03:28:22	Ravi Rajbhar	New			-	
	14-02-2022 11:46:55	Ravi Rajbhar	New			-	
	14-02-2022 11:46:42	Ravi Rajbhar	New	<u> </u>		·	
Previous	Date Time	Technician Name	Remark				
Complain History :	16-02-2022 10:32:32	Atique Salmani	use separate SMPS for terrace camera and issue resolved all working ok.				
1110t01 y •							