Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E : vallabhsecure@yah	100.00.111									
Service Status De	tails: VE7019									
Priority:	Low									
Created By:	Admin - Apurva Vajaria									
Complaint Mob. No. :	9930458545									
Technician Name :	Ishwar Meena			Teo:	chnician Mo	9165341500				
Ticket Type :	Complain	Date & Time		05	05-12-2022 04:37:48					
Vendor Details :				•				_		
Company Name/Client Name :	Shoppers Stop Ltd - Andheri	Custon:	mer's Mok	oile 99	9930458545		Name :		Yashwant S Savaratkar	
Address :				·						
Mumbai , , , 4000	58 , Maharashtra									
AMC Details :										
Expiry Date :	01-01-1970 05:30	01-01-1970 05:30:00			Type:					
Product Name:	CCTV									
Complain:	1st floor formal section 1 camera not working									
Technician Comment :	one camera issu resolved and angle set complated.									
Complain Operator :	Desktop - Apurva Vajaria									
Remark:	one camera issu resolved and angle set complated.									
Status History :	Date Time Technician Name Status Rema								Sign	
	05-12-2022 06:17:16 Ish		Ishwar M	eena	Completed	one camera issu resolved and angle set complated.		600		
	05-12-2022 04:37:57 Ishv		Ishwar M	ar Meena New					-	
Previous Complain History:	Date Time	Technician Name		Remark						
	27-09-2022 03:54:03	Atique Salmani		2 cameras issue resolved give proper earthing and working ok .						
	23-08-2022 10:48:14	Atique Salmani		1.Terrace tower side camera faulty water insert power .ohm ok also need 4*4 box when installed neew camera 2.terrece maingate bnc changed and working ok and there is no use also 4*4 box so camera female bnc dc rushted when camera changed also send 4*4 box . 3.parking camera used dome so need to chenged camera need bullet for same .it's on but after 5 to 6 mnt going off so need to changed camera. 4.1st floor angel settings done 5.1st floor disturbance issue resolved by bnc changed dvr end 6.4thbfloor camera blurr changed bnc but not issue resolved camera issue need to changed camera. 7.home section bluurr issue resolved by recocneetion . 8. Canteen camera ulba camera it's also being heat so sometimes on/ off so need to changed dome camera . use 1 vedo balloon .						