




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2429</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	7021711644																								
<b>Technician Name :</b>	Rishi Desai		<b>Technician Mobile :</b>	8369234074																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	15-12-2020 10:34:35																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mobile :	7021711644	Name :	Yogesh Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	some cameras are not working																								
<b>Technician Comment :</b>	All cameras are working ok, but some are showing blurr on Tv screen and need to do cable dressing near rack.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	All cameras are working ok, but some are showing blurr on Tv screen and need to do cable dressing near rack.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-12-2020 12:10:24</td><td>RishiDesai</td><td>Completed</td><td>All cameras are working ok, but some are showing blurr on Tv screen and need to do cable dressing near rack.</td><td></td></tr><tr><td>15-12-2020 10:34:49</td><td>RishiDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>15-12-2020 10:34:35</td><td>RishiDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-12-2020 12:10:24	RishiDesai	Completed	All cameras are working ok, but some are showing blurr on Tv screen and need to do cable dressing near rack.		15-12-2020 10:34:49	RishiDesai	New		-	15-12-2020 10:34:35	RishiDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
15-12-2020 12:10:24	RishiDesai	Completed	All cameras are working ok, but some are showing blurr on Tv screen and need to do cable dressing near rack.																						
15-12-2020 10:34:49	RishiDesai	New		-																					
15-12-2020 10:34:35	RishiDesai	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-07-2023 11:33:36</td><td>Shiva Meena</td><td>Xtedndar done oninstalled TV ok wark complete</td></tr><tr><td>26-05-2023 12:05:11</td><td>Atique Salmani</td><td>One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete	26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.											
Date Time	Technician Name	Remark																							
13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete																							
26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																							