




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2489																														
Priority :	High																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	7021711644																													
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																										
Ticket Type :	Complain	Date & Time :	28-12-2020 10:44:55																											
Vendor Details :																														
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mobile :	7021711644	Name :	Yogesh Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	install one supply which was purchased by client																													
Technician Comment :	new camera bullet installed working ok																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	new camera bullet installed working ok																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-01-2021 01:10:51</td><td>YogeshDesai</td><td>Completed</td><td>new camera bullet installed working ok</td><td></td></tr><tr><td>04-01-2021 10:50:53</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>28-12-2020 10:45:11</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>28-12-2020 10:44:55</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-01-2021 01:10:51	YogeshDesai	Completed	new camera bullet installed working ok		04-01-2021 10:50:53	YogeshDesai	New		-	28-12-2020 10:45:11	YogeshDesai	New		-	28-12-2020 10:44:55	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																										
04-01-2021 01:10:51	YogeshDesai	Completed	new camera bullet installed working ok																											
04-01-2021 10:50:53	YogeshDesai	New		-																										
28-12-2020 10:45:11	YogeshDesai	New		-																										
28-12-2020 10:44:55	YogeshDesai	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-07-2023 11:33:36</td><td>Shiva Meena</td><td>Xtedndar done oninstalled TV ok wark complete</td></tr><tr><td>26-05-2023 12:05:11</td><td>Atique Salmani</td><td>One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete	26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																
Date Time	Technician Name	Remark																												
13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete																												
26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																												