




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2973																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7021711644																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	12-04-2021 10:18:45																						
Vendor Details :																									
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mobile :	7021711644	Name :	Yogesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	connect monitor																								
Technician Comment :	monitor view issue resolved and ok working done (switcher port issue) 8 Ch DVR recording going on 23 day 4 Ch DVR recording going on 30 day																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	monitor view issue resolved and ok working done (switcher port issue) 8 Ch DVR recording going on 23 day 4 Ch DVR recording going on 30 day																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-04-2021 11:02:50</td><td>Ravi Rajbhar</td><td>Completed</td><td>monitor view issue resolved and ok working done (switcher port issue) 8 Ch DVR recording going on 23 day 4 Ch DVR recording going on 30 day</td><td></td></tr><tr><td>12-04-2021 10:19:08</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>12-04-2021 10:18:45</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-04-2021 11:02:50	Ravi Rajbhar	Completed	monitor view issue resolved and ok working done (switcher port issue) 8 Ch DVR recording going on 23 day 4 Ch DVR recording going on 30 day		12-04-2021 10:19:08	Ravi Rajbhar	New		-	12-04-2021 10:18:45	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
12-04-2021 11:02:50	Ravi Rajbhar	Completed	monitor view issue resolved and ok working done (switcher port issue) 8 Ch DVR recording going on 23 day 4 Ch DVR recording going on 30 day																						
12-04-2021 10:19:08	Ravi Rajbhar	New		-																					
12-04-2021 10:18:45	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-07-2023 11:33:36</td><td>Shiva Meena</td><td>Xtedndar done oninstalled TV ok wark complete</td></tr><tr><td>26-05-2023 12:05:11</td><td>Atique Salmani</td><td>One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete	26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.											
Date Time	Technician Name	Remark																							
13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete																							
26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																							