Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE3626							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	7021711644						
Technician Name :	Atique Salmani		Tech	nician Mobile : 8080922984			
Ticket Type :	Complain	Date & Time:	13-08	-2021 10:09:06			
Vendor Details :	Vendor Details :						
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mob	ile : 7021	711644	Name :	Yogesh Sir	
Address:							
Mumbai , , , , Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00			:			
Product Name :	CCTV						
Complain:	3 camera not working and dVR switch issue also						
Technician Comment :	3 camera issue tesolved 2 camera reconnection from camera end and use 02 pair and working ok and online hikconnect user id kamalsoc password.admin@123 2 phone apps installed and working ok.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	3 camera issue tesolved 2 camera reconnection from camera end and use 02 pair and working ok and online hikconnect user id kamalsoc password.admin@123 2 phone apps installed and working ok.						
Status History :	Date Time	Technician Name	Status	Re	mark	Sign	
	13-08-2021 12:05:23	Atique Salmani	Completed	3 camera issue tes reconnection from use 02 pair and wonline hikconnect password.admin@ installed and work	camera end and orking ok and user id kamalsoc 123 2 phone apps	KM:	
	13-08-2021 10:10:10	Atique Salmani	New			.	
	13-08-2021 10:09:06	Atique Salmani	New			-	

Previous Complain History :	Date Time	Technician Name	Remark	
	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete	
	26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.	