## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status De	tails: VE3857						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	7021711644						
Technician Name :	Neeraj Chauhan		Technicia	an Mobile : 8898885764			
Ticket Type:	Complain	Date & Time:	20-09-202	20-09-2021 11:45:05			
Vendor Details :							
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mobile :	7021711644		Name :	Yogesh Sir	
Address :							
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:	Type:			
<b>Product Name:</b>	CCTV						
Complain:	need to show recording						
Technician Comment :	DVD no. 1 /dvr no. 2 dvr time date automatic change and 2 dvr set date and time and 1 camera no video issue solved and use 1 video balun camera working okk and 2 camera video distributor issues solve and work done						
Complain Operator :	Desktop - Apurva Vajaria						
Remark :	DVD no. 1 /dvr no. 2 dvr time date automatic change and 2 dvr set date and time and 1 camera no video issue solved and use 1 video balun camera working okk and 2 camera video distributor issues solve and work done						
Status History :	Date Time	Technician Name	Status	I	Remark	Sign	
	20-09-2021 02:41:42	Neeraj Chauhan	Completed	date automat set date and no video issu- video balun c and 2 camera	or no. 2 dvr time cic change and 2 dv time and 1 camera e solved and use 1 camera working okla video distributor and work done		
	20-09-2021 11:45:31	Neeraj Chauhan	New			-	
	20-09-2021 11:45:05	Neeraj Chauhan	New			-	

Previous Complain History:	Date Time	Technician Name	Remark	
	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete	
	26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.	