

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4442															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	7021711644														
Technician Name :			Technician Mobile :												
Ticket Type :	Complain	Date & Time :	22-12-2021 02:48:15												
Vendor Details :															
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mobile :	7021711644	Name :	Yogesh Sir										
Address :															
Mumbai , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	DVR Date time issue -2012														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>22-12-2021 02:48:15</td><td></td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	22-12-2021 02:48:15		New		-
Date Time	Technician Name	Status	Remark	Sign											
22-12-2021 02:48:15		New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-07-2023 11:33:36</td><td>Shiva Meena</td><td>Xtedndar done oninstalled TV ok wark complete</td></tr><tr><td>26-05-2023 12:05:11</td><td>Atique Salmani</td><td>One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete	26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.	
Date Time	Technician Name	Remark													
13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete													
26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.													