




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7934																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7021711644																								
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																					
Ticket Type :	Complain	Date & Time :	23-03-2023 11:02:21																						
Vendor Details :																									
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mobile :	7021711644	Name :	Yogesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	need to show recording																								
Technician Comment :	5/03/2023 to 7/03/2023 recoding show to client and 2 camera no video issue need to check pending																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	5/03/2023 to 7/03/2023 recoding show to client and 2 camera no video issue need to check pending 24.03.23 - Camera no. 6 camera faulty cable ok camera need to change hikvision 4 in 1																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-03-2023 09:57:54</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>23-03-2023 01:13:56</td><td>Sonu Kumar</td><td>Work Pending</td><td>5/03/2023 to 7/03/2023 recoding show to client and 2 camera no video issue need to check pending</td><td></td></tr><tr><td>23-03-2023 11:02:28</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-03-2023 09:57:54	Sonu Kumar	New		-	23-03-2023 01:13:56	Sonu Kumar	Work Pending	5/03/2023 to 7/03/2023 recoding show to client and 2 camera no video issue need to check pending		23-03-2023 11:02:28	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
24-03-2023 09:57:54	Sonu Kumar	New		-																					
23-03-2023 01:13:56	Sonu Kumar	Work Pending	5/03/2023 to 7/03/2023 recoding show to client and 2 camera no video issue need to check pending																						
23-03-2023 11:02:28	Sonu Kumar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-07-2023 11:33:36</td><td>Shiva Meena</td><td>Xtedndar done oninstalled TV ok wark complete</td></tr><tr><td>26-05-2023 12:05:11</td><td>Atique Salmani</td><td>One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete	26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.											
Date Time	Technician Name	Remark																							
13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete																							
26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																							