




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8429</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	7021711644																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	26-05-2023 12:05:11																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mobile :	7021711644	Name :	Yogesh Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	1 camera recording issue																			
<b>Technician Comment :</b>	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-05-2023 04:39:55</td><td>Atique Salmani</td><td>Work Pending</td><td>One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.</td><td></td></tr><tr><td>26-05-2023 12:05:21</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-05-2023 04:39:55	Atique Salmani	Work Pending	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.		26-05-2023 12:05:21	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
26-05-2023 04:39:55	Atique Salmani	Work Pending	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																	
26-05-2023 12:05:21	Atique Salmani	New		-																

Previous Complain History :			
	Date Time	Technician Name	Remark
	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete
	27-04-2023 10:30:05		Camera chalu h par band chalu ho raha h Q ki dvr se lekar cat 6 ka cable dala gaya h aur us cable 4 camera ko joined kiya gaya h jiske waj se camera chalu band ho raha h.camera ko proper chalu karne ke har ek camera ka seperate cable dalna padega. Cctv working ok.