




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE9650</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	7021711644																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	AMC visiting	<b>Date &amp; Time :</b>	27-09-2023 12:31:11																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Kamal Apt CHSL	Customer's Mobile :	7021711644	Name :	Yogesh Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	Ppm																			
<b>Complain :</b>	CCTV PPM Need to do																			
<b>Technician Comment :</b>	Ther is only 2/2 cameras working boath dvr and night vision issue becz cable joint from every wing so cable camera need to changed also required quotation yogesh sir Also monitor faulty .																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Ther is only 2/2 cameras working boath dvr and night vision issue becz cable joint from every wing so cable camera need to changed also required quotation yogesh sir Also monitor faulty .																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-09-2023 03:36:31</td><td>Atique Salmani</td><td>Completed</td><td>Ther is only 2/2 cameras working boath dvr and night vision issue becz cable joint from every wing so cable camera need to changed also required quotation yogesh sir Also monitor faulty .</td><td></td></tr><tr><td>27-09-2023 12:31:17</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-09-2023 03:36:31	Atique Salmani	Completed	Ther is only 2/2 cameras working boath dvr and night vision issue becz cable joint from every wing so cable camera need to changed also required quotation yogesh sir Also monitor faulty .		27-09-2023 12:31:17	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
27-09-2023 03:36:31	Atique Salmani	Completed	Ther is only 2/2 cameras working boath dvr and night vision issue becz cable joint from every wing so cable camera need to changed also required quotation yogesh sir Also monitor faulty .																	
27-09-2023 12:31:17	Atique Salmani	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-07-2023 11:33:36</td><td>Shiva Meena</td><td>Xtedndar done oninstalled TV ok wark complete</td></tr><tr><td>26-05-2023 12:05:11</td><td>Atique Salmani</td><td>One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete	26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.						
Date Time	Technician Name	Remark																		
13-07-2023 11:33:36	Shiva Meena	Xtedndar done oninstalled TV ok wark complete																		
26-05-2023 12:05:11	Atique Salmani	One camera back side gate Dlink bullet camera installation done use one single vedeo baloon recording working ok Saroj bulding 2bullet camera off due to cable faulty cable distance 75/80 metr power ohms issue need to changed and also camera bracket break also need to changed camera and make a ruf plan and share in group for quotation.																		