

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE891																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7039779089																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	09-01-2020 10:04:24																						
Vendor Details :																									
Company Name/Client Name :	Ashford Royale	Customer's Mobile :	7039779089	Name :	Aftab																				
Address :																									
Mumbai , , , 400078 , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	reinstallation flat no: C 3404 complain flat no: 3602																								
Technician Comment :	Ashford royal c wing 3404 vdp reinstallation done and ok working and 500 cash collect and 3602 vdp adapter faulty but Clint side not change adapter it is pending																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Ashford royal c wing 3404 vdp reinstallation done and ok working and 500 cash collect and 3602 vdp adapter faulty but Clint side not change adapter it is pending																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-01-2020 04:44:13</td><td>Ravi Rajbhar</td><td>Completed</td><td>Ashford royal c wing 3404 vdp reinstallation done and ok working and 500 cash collect and 3602 vdp adapter faulty but Clint side not change adapter it is pending</td><td></td></tr><tr><td>09-01-2020 10:04:33</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>09-01-2020 10:04:25</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-01-2020 04:44:13	Ravi Rajbhar	Completed	Ashford royal c wing 3404 vdp reinstallation done and ok working and 500 cash collect and 3602 vdp adapter faulty but Clint side not change adapter it is pending		09-01-2020 10:04:33	Ravi Rajbhar	New		-	09-01-2020 10:04:25	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
09-01-2020 04:44:13	Ravi Rajbhar	Completed	Ashford royal c wing 3404 vdp reinstallation done and ok working and 500 cash collect and 3602 vdp adapter faulty but Clint side not change adapter it is pending																						
09-01-2020 10:04:33	Ravi Rajbhar	New		-																					
09-01-2020 10:04:25	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>17-01-2020 06:27:52</td><td></td><td></td></tr><tr><td>17-01-2020 06:27:52</td><td>Atique Salmani</td><td>there is only 2cameras blurr need 10 amps smps and one smps faulty collected and 2704 C wingout door camera installed working ok and c wing 2402 vdp complain solb. 5dvr checklist make</td></tr></tbody></table>					Date Time	Technician Name	Remark	17-01-2020 06:27:52			17-01-2020 06:27:52	Atique Salmani	there is only 2cameras blurr need 10 amps smps and one smps faulty collected and 2704 C wingout door camera installed working ok and c wing 2402 vdp complain solb. 5dvr checklist make											
Date Time	Technician Name	Remark																							
17-01-2020 06:27:52																									
17-01-2020 06:27:52	Atique Salmani	there is only 2cameras blurr need 10 amps smps and one smps faulty collected and 2704 C wingout door camera installed working ok and c wing 2402 vdp complain solb. 5dvr checklist make																							