Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE4544					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9619209853					
Technician Name :	Siddhesh Chavan		Technician Mobile :	n 8080922985		
Ticket Type:	Complain	Date & Time :	07-01-2022 02:34:18			
Vendor Details :						
Company Name/Client Name :	Octavius Cooperative Housing Society Ltd	Customer's Mobile :	961920985	53	Name :	Amar Ganesh
Address:						
Mumbai , , , , Ma	harashtra					
AMC Details:						
Expiry Date :	25-08-2020 12:00:00		Type:		Non-Comprehensive	
Product Name:	CCTV					
Complain:	remotely unable to view cameras					
Technician Comment :	wifi network issue and one camera survey done $50~MTR~Rj~6$ cable for camera and $40~MTR~cat~6$ and $rj6~for~tv$ view and one switcher and one hd camera and new piping					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	wifi network issue and one camera survey done 50 MTR Rj 6 cable for camera and 40 MTR cat 6 and rj6 for tv view and one switcher and one hd camera and new piping					
Status History :	Date Time	Technician Name	Status	Remark		Sign
	07-01-2022 06:03:03	Siddhesh Chavan	Completed	wifi network issue and one camera survey done 50 MTR Rj 6 cable for camera and 40 MTR cat 6 and rj6 for tv view and one switcher and one hd camera and new piping		
	07-01-2022 02:34:33	Siddhesh Chavan	New			-
	07-01-2022 02:34:18	Siddhesh Chavan	New			-
Previous Complain	Date Time	Technician Name	Remark			
History:	07-02-2022 04:02:50	Siddhesh Chavan	5/2/2022 5 to 6:30 recoding export in pendrive and 27 floor camera issue resolved			
	05-02-2022 02:10:29	Atique Salmani	one lift camera lift nmbr 4 issue resolved check extetender power ok and after that check camera ip delete and readd working ok. and one main gate camera fractuating issue resolved also 12 floor camera vedeo issue resolved by changed new bnc connector.			