




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE4556</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9619209853																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-01-2022 11:47:16																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Octavius Cooperative Housing Society Ltd	<b>Customer's Mobile :</b>	9619209853	<b>Name :</b>	Amar Ganesh																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	25-08-2020 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	Require some footage from december																								
<b>Technician Comment :</b>	lp gate 2 camera 3 days recoding export to pendrive and recoding lock																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	lp gate 2 camera 3 days recoding export to pendrive and recoding lock																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-01-2022 06:12:35</td><td>Siddhesh Chavan</td><td>Completed</td><td>lp gate 2 camera 3 days recoding export to pendrive and recoding lock</td><td></td></tr><tr><td>10-01-2022 11:47:37</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>10-01-2022 11:47:16</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-01-2022 06:12:35	Siddhesh Chavan	Completed	lp gate 2 camera 3 days recoding export to pendrive and recoding lock		10-01-2022 11:47:37	Siddhesh Chavan	New		-	10-01-2022 11:47:16	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
10-01-2022 06:12:35	Siddhesh Chavan	Completed	lp gate 2 camera 3 days recoding export to pendrive and recoding lock																						
10-01-2022 11:47:37	Siddhesh Chavan	New		-																					
10-01-2022 11:47:16	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-02-2022 04:02:50</td><td>Siddhesh Chavan</td><td>5/2/2022 5 to 6:30 recoding export in pendrive and 27 floor camera issue resolved</td></tr><tr><td>05-02-2022 02:10:29</td><td>Atique Salmani</td><td>one lift camera lift nmbr 4 issue resolved check extetender power ok and after that check camera ip delete and readd working ok. and one main gate camera fractuating issue resolved also 12 floor camera vedeo issue resolved by changed new bnc connector.</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-02-2022 04:02:50	Siddhesh Chavan	5/2/2022 5 to 6:30 recoding export in pendrive and 27 floor camera issue resolved	05-02-2022 02:10:29	Atique Salmani	one lift camera lift nmbr 4 issue resolved check extetender power ok and after that check camera ip delete and readd working ok. and one main gate camera fractuating issue resolved also 12 floor camera vedeo issue resolved by changed new bnc connector.											
Date Time	Technician Name	Remark																							
07-02-2022 04:02:50	Siddhesh Chavan	5/2/2022 5 to 6:30 recoding export in pendrive and 27 floor camera issue resolved																							
05-02-2022 02:10:29	Atique Salmani	one lift camera lift nmbr 4 issue resolved check extetender power ok and after that check camera ip delete and readd working ok. and one main gate camera fractuating issue resolved also 12 floor camera vedeo issue resolved by changed new bnc connector.																							