




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11015																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820985685																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	one_time	Date & Time :	04-03-2024 10:19:13																	
Vendor Details :																				
Company Name/Client Name :	Rutu Estate D9,10,11CHS Ltd	Customer's Mobile :	9820985685	Name :	Arun Patoli															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Access																			
Complain :	Access survey need to do																			
Technician Comment :	D11 lock missing with L bracket + biomax device touch not working. D10 all working ok door is not working propr need to repair by carpenter D9 all working door too fast need to repair by carpenter. All device password need to reset and make new admin																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	D11 lock missing with L bracket + biomax device touch not working. D10 all working ok door is not working propr need to repair by carpenter D9 all working door too fast need to repair by carpenter. All device password need to reset and make new admin																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-03-2024 11:12:31</td><td>Atique Salmani</td><td>Completed</td><td>D11 lock missing with L bracket + biomax device touch not working. D10 all working ok door is not working propr need to repair by carpenter D9 all working door too fast need to repair by carpenter. All device password need to reset and make new admin</td><td></td></tr><tr><td>04-03-2024 10:19:19</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-03-2024 11:12:31	Atique Salmani	Completed	D11 lock missing with L bracket + biomax device touch not working. D10 all working ok door is not working propr need to repair by carpenter D9 all working door too fast need to repair by carpenter. All device password need to reset and make new admin		04-03-2024 10:19:19	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
04-03-2024 11:12:31	Atique Salmani	Completed	D11 lock missing with L bracket + biomax device touch not working. D10 all working ok door is not working propr need to repair by carpenter D9 all working door too fast need to repair by carpenter. All device password need to reset and make new admin																	
04-03-2024 10:19:19	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody></tbody></table>					Date Time	Technician Name	Remark												
Date Time	Technician Name	Remark																		