




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE14114</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	8169148587																			
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	20-02-2025 10:52:47																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Ventura Alloy Kandivali New Office	Customer's Mobile :	8169148587	Name :	Ashish Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	13th floor cameras not able to see																			
<b>Technician Comment :</b>	13 th floor cmaera viewing ok on 12 floor office Client side divice dilit on pc then again ip add to pc on ok working done																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	13 th floor cmaera viewing ok on 12 floor office Client side divice dilit on pc then again ip add to pc on ok working done																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-02-2025 10:38:02</td><td>Ravi Rajbhar</td><td>Completed</td><td>13 th floor cmaera viewing ok on 12 floor office Client side divice dilit on pc then again ip add to pc on ok working done</td><td></td></tr><tr><td>26-02-2025 10:22:42</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-02-2025 10:38:02	Ravi Rajbhar	Completed	13 th floor cmaera viewing ok on 12 floor office Client side divice dilit on pc then again ip add to pc on ok working done		26-02-2025 10:22:42	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
26-02-2025 10:38:02	Ravi Rajbhar	Completed	13 th floor cmaera viewing ok on 12 floor office Client side divice dilit on pc then again ip add to pc on ok working done																	
26-02-2025 10:22:42	Ravi Rajbhar	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-03-2025 06:27:19</td><td>Siddhesh Chavan</td><td>Biometric ip block clint side and Bhiwandi network issue need to check and update</td></tr><tr><td>10-03-2025 02:25:44</td><td>Ravi Rajbhar</td><td>Bhimandi cctv system issue resolved and ok working done and one camera need on 13 floor bcz one cmaera on off And essl biometric attendance software issue resolved All ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	22-03-2025 06:27:19	Siddhesh Chavan	Biometric ip block clint side and Bhiwandi network issue need to check and update	10-03-2025 02:25:44	Ravi Rajbhar	Bhimandi cctv system issue resolved and ok working done and one camera need on 13 floor bcz one cmaera on off And essl biometric attendance software issue resolved All ok working done						
Date Time	Technician Name	Remark																		
22-03-2025 06:27:19	Siddhesh Chavan	Biometric ip block clint side and Bhiwandi network issue need to check and update																		
10-03-2025 02:25:44	Ravi Rajbhar	Bhimandi cctv system issue resolved and ok working done and one camera need on 13 floor bcz one cmaera on off And essl biometric attendance software issue resolved All ok working done																		