Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE10805 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9137852143 **No. : Technician Name** Sonu Kumar **Technician Mobile :** 8454016444 Complain Date & Time : 08-02-2024 11:04:42 **Ticket Type :** Vendor Details : Tivon Park Customer's Mobile 9137852143 Ashok Yadav Company Name : Name/Client Name E/F/G/H Wing Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: F wing 6 cameras off issue 6 camera off issue resolved working ok and 2 camera angle seting done and h wing 1 box Technician **Comment**: install all working ok Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 6 camera off issue resolved working ok and 2 camera angle seting done and h wing 1 box install all working ok **Status History : Date Time Technician Name** Status Remark Sign 08-02-2024 05:06:54 Sonu Kumar Completed 6 camera off issue resolved working ok and 2 camera angle seting done and h wing 1 box install all working ok 08-02-2024 11:04:49 Sonu Kumar New Previous **Date Time Technician Name** Remark **Complain History** 31-01-2024 Shiva Meena Lift cabling work completed and camera install done 80 mtr 11:39:50 cabling done H - 802 intercom install done 15-01-2024 Atique Salmani G wi g lift camera issue resolved by reconnection from lift top 11:12:23 And G2 intercom connection done working ok And H 802 no one at home after one week And h703 from duct to falte cable missing so user rj6 cable for intercom working ok also I installed phone .