## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE10280							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8169697919						
Technician Name	Atique Salmani		Technici	an Mobile : 8080922984			
Ticket Type:	Complain	Date & Time :	15-12-20	15-12-2023 10:31:11			
Vendor Details :							
Company Name/Client Name :	Dun Apts	Customer's Mobile	: 8169697	'919	Name:	Atul Sir	
Address:							
Mumbai,,,, Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:0	Type:	Type:				
<b>Product Name:</b>	Intercom						
Complain:	flat no. 1001 and 1002 intercom not working						
Technician Comment :	1001/2 allready working only chek form flate side and timing resetbecz it was 15 mnt delay so from 1st floor system crone 1st port set working ok.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	1001/2 allready working only chek form flate side and timing resetbecz it was 15 mnt delay so from 1st floor system crone 1st port set working ok.						
Status History :	Date Time	Technician Name	Status	Remark Sign  1001 /2 allready working only chek form flate side and timing resetbecz it was 15 mnt delay so from 1st floor system crone 1st port set working ok.		Sign	
	18-12-2023 02:21:17	Atique Salmani	Completed			leli t	
	18-12-2023 10:16:00	Atique Salmani	New			-	
Previous Complain History :	Date Time	Technician Name		Remark			
	04-12-2023 10:32:51	Ravi Rajbhar	line issue res	203 intercom line ok instrument issue and security table two line issue resolved 91,92 cable check then repunching both side then ok working done			
	01-11-2023 10:03:18	DilshadKhan	103 and 502	103 and 502 and 603 and 1003 resolved and solve			