Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Det	tails: VE8492						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8169697919						
Technician Name:	Shiva Meena		Technicia	Technician Mobile: 7489567735			
Ticket Type :	Complain	Date & Time :	03-06-2023 04:56:54				
Vendor Details :		•	-				
Company Name/Client Name :	Dun Apts	Customer's Mobile :	: 8169697919		Name:	Atul Sir	
Address:							
Mumbai , , , , Mah	ıarashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30	Type:					
Product Name:	CCTV						
Complain:	4 cameras off issue						
Technician Comment :	300 cebal and get camera cebal folty and 16 no. Camera cebal pawer isu band chalu aal camera ok wark complete						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	300 cebal and get camera cebal folty and 16 no. Camera cebal pawer isu band chalu aal camera ok wark complete						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	03-06-2023 05:58:1	0 Shiva Meena	Completed	300 cebal and get camera cebal folty and 16 no. Camera cebal pawer isu band chalu aal camera ok wark complete		Amyra	
	03-06-2023 04:57:1	0 Shiva Meena	New			-	
Previous Complain History:	Date Time	Technician Name		Remark			
	08-06-2023 02:51:30	2:51:30 SubhashGurav		Main Gate Camera no. 7 Cable Faulty Required 170 meter cable. Best Sub Station Camera No. 15 cable Faulty Required 50 meter cable. Camera no. 9 Camera sensor issue Required New Bullet Camera. And Required 15 pair video balloon for Proper dressing DVR And Camera side			
	24-05-2023 02:02:15	Kalpesh SubhashGurav	406 - Intercom line switched on (The flat owner will bring the phone) 703 - Intercom connection is not required. 706 - Line OK 104 - Line OK 1102 - Lock 204 - Intercom line switched on (The flat owner will bring the phone) Main Lobby Security Ext.91/92 Roset box Connected and turned on.				