

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12112																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8169544882																													
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																										
Ticket Type :	Call Basis	Date & Time :	10-07-2024 11:51:53																											
Vendor Details :																														
Company Name/Client Name :	Shantilal & Co.	Customer's Mobile :	8169544882	Name :	Ayush																									
Address :																														
Mumbai , , , 400067 , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	need to check camera and intercom																													
Technician Comment :	need to change all intercom cables need install cat 6 armand cable for 305 system working ok and cables also side joined																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	need to change all intercom cables need install cat 6 armand cable for 305 system working ok and cables also side joined																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-08-2024 01:08:30</td><td>Siddhesh Chavan</td><td>Completed</td><td></td><td>-</td></tr><tr><td>11-07-2024 02:36:50</td><td>Siddhesh Chavan</td><td>Client Side</td><td>need to change all intercom cables need install cat 6 armand cable for 305 system working ok and cables also side joined</td><td></td></tr><tr><td>11-07-2024 02:29:49</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>11-07-2024 11:23:41</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-08-2024 01:08:30	Siddhesh Chavan	Completed		-	11-07-2024 02:36:50	Siddhesh Chavan	Client Side	need to change all intercom cables need install cat 6 armand cable for 305 system working ok and cables also side joined		11-07-2024 02:29:49	Siddhesh Chavan	New		-	11-07-2024 11:23:41	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
14-08-2024 01:08:30	Siddhesh Chavan	Completed		-																										
11-07-2024 02:36:50	Siddhesh Chavan	Client Side	need to change all intercom cables need install cat 6 armand cable for 305 system working ok and cables also side joined																											
11-07-2024 02:29:49	Siddhesh Chavan	New		-																										
11-07-2024 11:23:41	Siddhesh Chavan	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>16-08-2024 10:27:58</td><td>Atique Salmani</td><td>Total 3 camera off becuz one terrace camera 2 pair cable shor so it was shorting plus minus so used only 2 pair for power and working ok all 16 camera one 1floor camera need to shift according to kamlesh sir becuz there is new partition so need to shift .</td></tr><tr><td>12-08-2024 10:41:27</td><td>Atique Salmani</td><td>There was maine swich was off epbax system so all phone was off now on and mark the swich as pls don't of this swich working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	16-08-2024 10:27:58	Atique Salmani	Total 3 camera off becuz one terrace camera 2 pair cable shor so it was shorting plus minus so used only 2 pair for power and working ok all 16 camera one 1floor camera need to shift according to kamlesh sir becuz there is new partition so need to shift .	12-08-2024 10:41:27	Atique Salmani	There was maine swich was off epbax system so all phone was off now on and mark the swich as pls don't of this swich working ok.																
Date Time	Technician Name	Remark																												
16-08-2024 10:27:58	Atique Salmani	Total 3 camera off becuz one terrace camera 2 pair cable shor so it was shorting plus minus so used only 2 pair for power and working ok all 16 camera one 1floor camera need to shift according to kamlesh sir becuz there is new partition so need to shift .																												
12-08-2024 10:41:27	Atique Salmani	There was maine swich was off epbax system so all phone was off now on and mark the swich as pls don't of this swich working ok.																												