## **Vallabh Enterprises**

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \mathbf{W}: \text{www.vallabhenterprises.com} \\ \mathbf{E}: \text{vallabhsecure@yahoo.co.in}$ 

Service Status De	tails: VE3877					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob.	7738881588					
Technician Name :	Atique Salmani		Technician Mobile		8080922984	
Ticket Type :	Complain	Date & Time :	22-09-2021 11:47:07			
Vendor Details :						
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	7738881588		Name :	Aziza Madam
Address :						
Mumbai , , , 4000	064 , Maharashtra					
AMC Details :						
Expiry Date :	30-11-2020 12:00:0	0	Type:		Non-Comprehensive	
<b>Product Name:</b>	cCTV-Intercom					
Complain:	1 hdd installation + 1 phone installation					
Technician Comment :	security desk new phone installd and check working ok and also installed 4 tb hdd recording working ok and boath dvr frame rate and bit rate reset .make new checklist .					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	security desk new phone installd and check working ok and also installed 4 tb hdd recording working ok and boath dvr frame rate and bit rate reset .make new checklist .					
<b>Status History:</b>	Date Time	Technician Name	Status	Remark		Sign
	22-09-2021 02:27:37	Atique Salmani	Completed	security desk new phone installd and check working ok and also installed 4 tb hdd recording working ok and boath dvr frame rate and bit rate reset .make new checklist .		
	22-09-2021 11:47:35	Atique Salmani	New			-
	22-09-2021 11:47:08	Atique Salmani	New			-
Previous Complain History :	Date Time	Technician Name	Remark			
	22-09-2021 11:50:01	Atique Salmani	out door bell camera installed new and also give demo how to oprate . also Receved payment 2200/			
	17-09-2021 06:17:11	Atique Salmani	Lift camera suplly given from top of the lift now given from dvr ends and keep it on under observation and aslo refilled camera nmbr $4\ \mathrm{bnc}$ conector also check 701 intercom working ok .			