


# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE4085</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	7738881588				
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	21-10-2021 03:38:44		
<b>Vendor Details :</b>					
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	7738881588	Name :	Aziza Madam
<b>Address :</b>					
Mumbai , , , 400064 , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	30-11-2020 12:00:00		<b>Type :</b>	Non-Comprehensive	
<b>Product Name :</b>	Ppm				
<b>Complain :</b>	CCTV/Intercom/VDP				
<b>Technician Comment :</b>	all intercom ok and ppm done and 1901 Lin ok phone issue 14 floor vdp SMPS faulty and need to Changed and check dvr all make check list report also check hdd bad sector and status normal all ok hdd functionioing properly .ppm done . one camera water insert remooved and cleaned but working on night mode so need to changed this also becoz bullet camera ir sensor faulty so need to changed .				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	all intercom ok and ppm done and 1901 Lin ok phone issue 14 floor vdp SMPS faulty and need to Changed and check dvr all make check list report also check hdd bad sector and status normal all ok hdd functionioing properly .ppm done . one camera water insert remooved and cleaned but working on night mode so need to changed this also becoz bullet camera ir sensor faulty so need to changed .				

<b>Status History :</b>	<b>Date Time</b>	<b>Technician Name</b>	<b>Status</b>	<b>Remark</b>	<b>Sign</b>
	21-10-2021 06:05:56	Atique Salmani	Completed	all intercom ok and ppm done and 1901 Lin ok phone issue 14 floor vdp SMPS faulty and need to Changed and check dvr all make check list report also check hdd bad sector and status normal all ok hdd functionioing properly .ppm done . one camera water insert remooved and cleaned but working on night mode so need to changed this also becoz bullet camera ir sensor faulty so need to changed .	
	21-10-2021 03:38:57	Atique Salmani	New		-
	21-10-2021 03:38:44	Atique Salmani	New		-
<b>Previous Complain History :</b>	<b>Date Time</b>	<b>Technician Name</b>	<b>Remark</b>		
	15-01-2022 04:42:50	Atique Salmani	make check list and all flor cameras check all working ok ppm done .		
	15-01-2022 04:41:19	Atique Salmani	1902 line ok instrument issue some notice issue and 3 cameras issue resolved all working ok.		