







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4538																																								
Priority :	Low																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	8369359090																																							
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																																				
Ticket Type :	Complain	Date & Time :	06-01-2022 11:36:38																																					
Vendor Details :																																								
Company Name/Client Name :	Gomti Co Op Hsg Society	Customer's Mobile :	8369359090	Name :	Bharat Purohit																																			
Address :																																								
Mumbai , Mandpeshwar Road, Divine Home Colony, Navagaon, Dahisar West, Mumbai, Maharashtra, India , , , Maharashtra																																								
AMC Details :																																								
Expiry Date :	18-12-2020 12:00:00		Type :	Non-Comprehensive																																				
Product Name :	CCTV																																							
Complain :	Rack screw fitting																																							
Technician Comment :	ruk installation done .stand by dvr and power supply install . HDD backup not dilete. All camera working .																																							
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :	ruk installation done .stand by dvr and power supply install . HDD backup not dilete. All camera working .																																							
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-01-2022 06:24:04</td><td>ChandanYadav</td><td>Completed</td><td>ruk installation done .stand by dvr and power supply install . HDD backup not dilete. All camera working .</td><td></td></tr><tr><td>08-01-2022 04:23:32</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>07-01-2022 02:43:54</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>06-01-2022 12:03:49</td><td>ChandanYadav</td><td>Work Pending</td><td>rack temporary fit and need to send someone and reinstall rack</td><td></td></tr><tr><td>06-01-2022 11:36:55</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>06-01-2022 11:36:38</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-01-2022 06:24:04	ChandanYadav	Completed	ruk installation done .stand by dvr and power supply install . HDD backup not dilete. All camera working .		08-01-2022 04:23:32	ChandanYadav	New		-	07-01-2022 02:43:54	ChandanYadav	New		-	06-01-2022 12:03:49	ChandanYadav	Work Pending	rack temporary fit and need to send someone and reinstall rack		06-01-2022 11:36:55	ChandanYadav	New		-	06-01-2022 11:36:38	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
08-01-2022 06:24:04	ChandanYadav	Completed	ruk installation done .stand by dvr and power supply install . HDD backup not dilete. All camera working .																																					
08-01-2022 04:23:32	ChandanYadav	New		-																																				
07-01-2022 02:43:54	ChandanYadav	New		-																																				
06-01-2022 12:03:49	ChandanYadav	Work Pending	rack temporary fit and need to send someone and reinstall rack																																					
06-01-2022 11:36:55	ChandanYadav	New		-																																				
06-01-2022 11:36:38	ChandanYadav	New		-																																				

Previous Complain History :			
	Date Time	Technician Name	Remark
	12-02-2022 06:53:23	Ravi Rajbhar	ppm done of CCTV system all ok working done
	12-02-2022 10:10:25	Ravi Rajbhar	stand by DVR removed and return office and repair DVR install and ok working done