

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11844															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9820223640														
Technician Name :		Technician Mobile :													
Ticket Type :	Complain	Date & Time :	07-06-2024 02:08:24												
Vendor Details :															
Company Name/Client Name :	B.BIPINKUMAR & CO.	Customer's Mobile :	9820223640	Name :	Bhavesh Sir										
Address :															
Mumbai , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00	Type :													
Product Name :	Access														
Complain :	when button press door not getting open quickly and require some bell to know the door is open														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-01-1970 05:30:00</td><td></td><td></td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-01-1970 05:30:00				-
Date Time	Technician Name	Status	Remark	Sign											
01-01-1970 05:30:00				-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-04-2024 12:48:52</td><td>Siddhesh Chavan</td><td>access lock issue resolved panel side recontion and lock working ok Biometric lan contion issue resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-04-2024 12:48:52	Siddhesh Chavan	access lock issue resolved panel side recontion and lock working ok Biometric lan contion issue resolved				
Date Time	Technician Name	Remark													
12-04-2024 12:48:52	Siddhesh Chavan	access lock issue resolved panel side recontion and lock working ok Biometric lan contion issue resolved													