

# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

| <b>Service Status Details : VE8379</b> |   |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
|--|---|--|----------------------------|---------------|------------|-----------|-----------------|--------|---------------------|----------------|---|---------------------|-------------|--|---|---------------------|---------------|-----|--|---|
| <b>Priority :</b>                      | Low   |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Created By :</b>                    | Admin - Apurva Vajaria  |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Complaint Mob. No. :</b>            | 9892939539  |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Technician Name :</b>               | Santosh Pathak  |  | <b>Technician Mobile :</b> | 8080922980    |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Ticket Type :</b>                   | Complain  | <b>Date &amp; Time :</b>   | 19-05-2023 10:33:30        |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Vendor Details :</b>                |   |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Company Name/Client Name :</b>      | P V Enterprises   | <b>Customer's Mobile :</b>   | 9892939539                 | <b>Name :</b> | Bhavik Sir |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Address :</b>                       |   |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| Mumbai , , , , Maharashtra             |   |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>AMC Details :</b>                   |   |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Expiry Date :</b>                   | 01-01-1970 05:30:00   |  | <b>Type :</b>              |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Product Name :</b>                  | CCTV  |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Complain :</b>                      | 2 camera not working cash collect 750/  |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Technician Comment :</b>            |   |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Complain Operator :</b>             | Desktop - Apurva Vajaria  |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Remark :</b>                        | Inzmam visited - New smps installed and 4 cameras not working issue resolved.   |  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Status History :</b>                | <table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-05-2023 04:02:49</td><td>SantoshPathak</td><td>Completed</td><td></td><td>-</td></tr><tr><td>19-05-2023 10:33:55</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr></tbody></table>   |  |                            |               |            | Date Time | Technician Name | Status | Remark              | Sign           | 27-05-2023 04:02:49   | SantoshPathak       | Completed   |  | - | 19-05-2023 10:33:55 | SantoshPathak | New |  | - |
| Date Time                              | Technician Name   | Status   | Remark                     | Sign          |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| 27-05-2023 04:02:49                    | SantoshPathak   | Completed  |                            | -             |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| 19-05-2023 10:33:55                    | SantoshPathak   | New  |                            | -             |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| <b>Previous Complain History :</b>     | <table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-09-2022 11:23:35</td><td>Neeraj Chauhan</td><td>1 no video camera issue solve and camera working okk. 750 visiting charges collect.</td></tr><tr><td>12-03-2022 10:23:33</td><td>YogeshDesai</td><td>Two cameras and door excess sloved as the power supply was faulty. new power supply has been installed camera working and door to. faulty supply given back to client.</td></tr></tbody></table> |  |                            |               |            | Date Time | Technician Name | Remark | 06-09-2022 11:23:35 | Neeraj Chauhan | 1 no video camera issue solve and camera working okk. 750 visiting charges collect. | 12-03-2022 10:23:33 | YogeshDesai | Two cameras and door excess sloved as the power supply was faulty. new power supply has been installed camera working and door to. faulty supply given back to client. |   |                     |               |     |  |   |
| Date Time                              | Technician Name   | Remark   |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| 06-09-2022 11:23:35                    | Neeraj Chauhan  | 1 no video camera issue solve and camera working okk. 750 visiting charges collect.  |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |
| 12-03-2022 10:23:33                    | YogeshDesai   | Two cameras and door excess sloved as the power supply was faulty. new power supply has been installed camera working and door to. faulty supply given back to client. |                            |               |            |           |                 |        |                     |                |   |                     |             |  |   |                     |               |     |  |   |