







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2982</b>																																								
<b>Priority :</b>	Low																																							
<b>Created By :</b>	Admin - Apurva Vajaria																																							
<b>Complaint Mob. No. :</b>	9167344895																																							
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																																				
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	14-04-2021 10:26:12																																					
<b>Vendor Details :</b>																																								
Company Name/Client Name :	Konark CHS Ltd	Customer's Mobile :	9167344895	Name :	Bijal Sir																																			
<b>Address :</b>																																								
Mumbai , , , , Maharashtra																																								
<b>AMC Details :</b>																																								
Expiry Date :	31-03-2021 12:00:00		Type :	Comprehensive																																				
<b>Product Name :</b>	Intercom																																							
<b>Complain :</b>	new intercom system installation																																							
<b>Technician Comment :</b>	32 line intercom crystal system also install and all flat programming done also and all flat ok working confirm to brijal ( 601 port issue and new port uesd 24)																																							
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																							
<b>Remark :</b>	32 line intercom crystal system also install and all flat programming done also and all flat ok working confirm to brijal ( 601 port issue and new port uesd 24)																																							
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-06-2021 05:42:36</td><td>Ravi Rajbhar</td><td>Completed</td><td>32 line intercom crystal system also install and all flat programming done also and all flat ok working confirm to brijal ( 601 port issue and new port uesd 24)</td><td></td></tr><tr><td>21-06-2021 02:27:58</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>15-06-2021 10:01:01</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>14-04-2021 12:53:27</td><td>Ravi Rajbhar</td><td>Client Side</td><td>work pending client side</td><td></td></tr><tr><td>14-04-2021 10:26:23</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>14-04-2021 10:26:13</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-06-2021 05:42:36	Ravi Rajbhar	Completed	32 line intercom crystal system also install and all flat programming done also and all flat ok working confirm to brijal ( 601 port issue and new port uesd 24)		21-06-2021 02:27:58	Ravi Rajbhar	New		-	15-06-2021 10:01:01	Ravi Rajbhar	New		-	14-04-2021 12:53:27	Ravi Rajbhar	Client Side	work pending client side		14-04-2021 10:26:23	Ravi Rajbhar	New		-	14-04-2021 10:26:13	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
21-06-2021 05:42:36	Ravi Rajbhar	Completed	32 line intercom crystal system also install and all flat programming done also and all flat ok working confirm to brijal ( 601 port issue and new port uesd 24)																																					
21-06-2021 02:27:58	Ravi Rajbhar	New		-																																				
15-06-2021 10:01:01	Ravi Rajbhar	New		-																																				
14-04-2021 12:53:27	Ravi Rajbhar	Client Side	work pending client side																																					
14-04-2021 10:26:23	Ravi Rajbhar	New		-																																				
14-04-2021 10:26:13	Ravi Rajbhar	New		-																																				

Previous Complain History :			
	Date Time	Technician Name	Remark
	31-07-2023 12:56:14	Atique Salmani	5 cameras issue resolved power was shorting so supply was blinking so checked and reconnection 2 cameras all 16 cameras working ok. ***All outside cameras working on joint and without box so need to changed cameras +box
	11-07-2023 12:49:54	PravinJagade	5 meter HDMI cable installation done. DVR to tv