




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5833																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9167344895																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	30-06-2022 04:02:05																											
Vendor Details :																														
Company Name/Client Name :	Konark CHS Ltd	Customer's Mobile :	9167344895	Name :	Bijal Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	31-03-2021 12:00:00		Type :	Comprehensive																										
Product Name :	CCTV																													
Complain :	main gate camera off issue																													
Technician Comment :	camera reconnection done working ok but in camera water inserted and also camera cable too shrt so need to changed camera and also 4+1 cable too short need to joint 2 metr cable also 4*4 box.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	camera reconnection done working ok but in camera water inserted and also camera cable too shrt so need to changed camera and also 4+1 cable too short need to joint 2 metr cable also 4*4 box.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-07-2022 04:22:16</td><td>Atique Salmani</td><td>Closed</td><td></td><td>-</td></tr><tr><td>30-06-2022 04:48:30</td><td>Atique Salmani</td><td>Completed</td><td>camera reconnection done working ok but in camera water inserted and also camera cable too shrt so need to changed camera and also 4+1 cable too short need to joint 2 metr cable also 4*4 box.</td><td></td></tr><tr><td>30-06-2022 04:02:18</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>30-06-2022 04:02:06</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-07-2022 04:22:16	Atique Salmani	Closed		-	30-06-2022 04:48:30	Atique Salmani	Completed	camera reconnection done working ok but in camera water inserted and also camera cable too shrt so need to changed camera and also 4+1 cable too short need to joint 2 metr cable also 4*4 box.		30-06-2022 04:02:18	Atique Salmani	New		-	30-06-2022 04:02:06	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
01-07-2022 04:22:16	Atique Salmani	Closed		-																										
30-06-2022 04:48:30	Atique Salmani	Completed	camera reconnection done working ok but in camera water inserted and also camera cable too shrt so need to changed camera and also 4+1 cable too short need to joint 2 metr cable also 4*4 box.																											
30-06-2022 04:02:18	Atique Salmani	New		-																										
30-06-2022 04:02:06	Atique Salmani	New		-																										

**Previous
Complain
History :**

Date Time	Technician Name	Remark
24-06-2022 04:18:01	Siddhesh Chavan	2 nd floor camera working ok
15-06-2022 10:49:34	Atique Salmani	