Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE5979 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9167344895 **No. :** Technician Ravi Rajbhar **Technician Mobile :** 8080922965 Name : Complain 18-07-2022 03:45:51 **Ticket Type :** Date & Time : **Vendor Details :** Konark CHS Ltd Customer's Mobile : 9167344895 Bijal Sir Company Name : Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-03-2021 12:00:00 Comprehensive Expiry Date : Type : **Product Name :** CCTV **Complain**: 5 camera not working + door alignment issue 5 camera also ok working done one camera main door reconnection and glass door em lock **Technician** aliment issue resolved and biometric acesss divice 3 parson finger add **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 5 camera also ok working done one camera main door reconnection and glass door em lock aliment issue resolved and biometric acesss divice 3 parson finger add **Status History : Date Time Technician Name** Status Remark Sign 18-07-2022 Ravi Rajbhar Completed 5 camera also ok working done 04:38:39 one camera main door PAL. reconnection and glass door em lock aliment issue resolved and biometric acesss divice 3 parson finger add 18-07-2022 Ravi Rajbhar New 03:46:35 18-07-2022 Ravi Rajbhar New 03:45:51 **Previous Date Time Technician Name** Remark Complain 02-07-2022 Siddhesh Chavan tv viewing working ok and one camera no video issue resolved **History** : 04:57:23 and 2 days 2 clips recoding export in pendrive and all camera working ok 30-06-2022 Atique Salmani camera reconnection done working ok but in camera water inserted and also camera cable too shrt so need to changed 04:02:05 camera and also 4+1 cable too short need to joint 2 metr cable also 4*4 box.