Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE861 **Priority** : High **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9167344895 **No. : Technician** Ravi Rajbhar **Technician Mobile :** 8080922965 Name : Complain 06-01-2020 03:08:21 **Ticket Type :** Date & Time : **Vendor Details :** Konark CHS Ltd Customer's Mobile : 9167344895 Bijal Sir Company Name : Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-03-2021 12:00:00 Comprehensive Expiry Date : Type : **Product Name :** VDP **Complain**: Need to 3 cards flat no: 302 VDp and intercom issue 302 vdp check but vdp faulty not repaired and intercom issue reslvoed but ex .no change (1204 **Technician Comment** : - 302) (0801- 401) and 202 ok working and 201 line ok istument issue and 101 wering missing Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 302 vdp check but vdp faulty not repaired and intercom issue reslvoed but ex .no change (1204 - 302) (0801- 401) and 202 ok working and 201 line ok istument issue and 101 wering missing **Status History : Date Time Technician Name** Status Remark Sign 07-01-2020 Ravi Rajbhar Completed 302 vdp check but vdp faulty 05:59:12 not repaired and intercom issue reslvoed but ex .no change (1204 - 302) (0801-401) and 202 ok working and 201 line ok istument issue and 101 wering missing 07-01-2020 Ravi Rajbhar New 01:52:25 06-01-2020 Ravi Rajbhar New 03:08:21 Previous **Date Time Technician Name** Remark Complain 31-07-2023 12:56:14 **History** : Atique Salmani 5 cameras issue resolved power was shorting so supply was blinking so checked and reconnection 2 cameras all 16 cameras working ok. ***All outside cameras working on joint and without box so need to changed cameras +box 11-07-2023 12:49:54 5 meter HDMI cable installation done. DVR to tv PravinJagade