




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13135																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9224657132																			
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																
Ticket Type :	Complain	Date & Time :	29-10-2024 11:45:16																	
Vendor Details :																				
Company Name/Client Name :	Bhoomi Association	Customer's Mobile :	9224657132	Name :	Bipin Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	C wing backside gate repaired camera need to install and standby need to collect																			
Technician Comment :	C wing main gate side camera install done.camera working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	C wing main gate side camera install done.camera working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-10-2024 01:02:32</td><td>ChandanYadav</td><td>Completed</td><td>C wing main gate side camera install done.camera working ok.</td><td></td></tr><tr><td>29-10-2024 11:45:46</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-10-2024 01:02:32	ChandanYadav	Completed	C wing main gate side camera install done.camera working ok.		29-10-2024 11:45:46	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
29-10-2024 01:02:32	ChandanYadav	Completed	C wing main gate side camera install done.camera working ok.																	
29-10-2024 11:45:46	ChandanYadav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>17-10-2024 05:59:27</td><td>Siddhesh Chavan</td><td>Stand by Camera install And old Camera take to office repring</td></tr><tr><td>11-09-2024 01:40:21</td><td>ChandanYadav</td><td>E wing back side camera pinkish issue solve and main gate side camera pinkish issue found also installed client to same. 11/10/24 timing 6:48 NVR gone off due to spike guard power off and due to recording also not done and 16/10/24 timing 4:50 spike guard power on and NVR working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	17-10-2024 05:59:27	Siddhesh Chavan	Stand by Camera install And old Camera take to office repring	11-09-2024 01:40:21	ChandanYadav	E wing back side camera pinkish issue solve and main gate side camera pinkish issue found also installed client to same. 11/10/24 timing 6:48 NVR gone off due to spike guard power off and due to recording also not done and 16/10/24 timing 4:50 spike guard power on and NVR working ok						
Date Time	Technician Name	Remark																		
17-10-2024 05:59:27	Siddhesh Chavan	Stand by Camera install And old Camera take to office repring																		
11-09-2024 01:40:21	ChandanYadav	E wing back side camera pinkish issue solve and main gate side camera pinkish issue found also installed client to same. 11/10/24 timing 6:48 NVR gone off due to spike guard power off and due to recording also not done and 16/10/24 timing 4:50 spike guard power on and NVR working ok																		