







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12025																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9082372422																													
Technician Name :	Manoj Polekar		Technician Mobile :	7385366458																										
Ticket Type :	New Installation	Date & Time :	29-06-2024 12:30:29																											
Vendor Details :																														
Company Name/Client Name :	Kokan Residency	Customer's Mobile :	9082372422	Name :	Chandrakant Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	3 cameras new installation with cabling																													
Technician Comment :	One camera installation pending work completed																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	One camera installation pending work completed																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-07-2024 06:16:43</td><td>ManojPolekar</td><td>Completed</td><td>One camera installation pending work completed</td><td></td></tr><tr><td>01-07-2024 10:19:16</td><td>ManojPolekar</td><td>New</td><td></td><td>-</td></tr><tr><td>29-06-2024 11:32:47</td><td>ManojPolekar</td><td>Work Pending</td><td>4 camera cabling done and 1 main date camera cable pending and 1 camera and 134 mtr cable and video issue and 4/4 box handovar to client</td><td></td></tr><tr><td>29-06-2024 12:30:37</td><td>ManojPolekar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-07-2024 06:16:43	ManojPolekar	Completed	One camera installation pending work completed		01-07-2024 10:19:16	ManojPolekar	New		-	29-06-2024 11:32:47	ManojPolekar	Work Pending	4 camera cabling done and 1 main date camera cable pending and 1 camera and 134 mtr cable and video issue and 4/4 box handovar to client		29-06-2024 12:30:37	ManojPolekar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
01-07-2024 06:16:43	ManojPolekar	Completed	One camera installation pending work completed																											
01-07-2024 10:19:16	ManojPolekar	New		-																										
29-06-2024 11:32:47	ManojPolekar	Work Pending	4 camera cabling done and 1 main date camera cable pending and 1 camera and 134 mtr cable and video issue and 4/4 box handovar to client																											
29-06-2024 12:30:37	ManojPolekar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-06-2024 03:37:23</td><td>Neeraj Chauhan</td><td>Ppm done and dvr Power supply change</td></tr><tr><td>01-03-2024 05:52:25</td><td>Atique Salmani</td><td>Total 5 cameras clean also dvr rack clean all working ok one bullet camera coming blurry need to changed bec2 too old and also cement cover on lence</td></tr></tbody></table>					Date Time	Technician Name	Remark	22-06-2024 03:37:23	Neeraj Chauhan	Ppm done and dvr Power supply change	01-03-2024 05:52:25	Atique Salmani	Total 5 cameras clean also dvr rack clean all working ok one bullet camera coming blurry need to changed bec2 too old and also cement cover on lence																
Date Time	Technician Name	Remark																												
22-06-2024 03:37:23	Neeraj Chauhan	Ppm done and dvr Power supply change																												
01-03-2024 05:52:25	Atique Salmani	Total 5 cameras clean also dvr rack clean all working ok one bullet camera coming blurry need to changed bec2 too old and also cement cover on lence																												