

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7625																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9884958343																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	14-02-2023 10:07:34																	
Vendor Details :																				
Company Name/Client Name :	Bombay Dyeing Worli	Customer's Mobile :	9884958343	Name :	Chandraraja Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																
Product Name :	Access																			
Complain :	access beep sound issue																			
Technician Comment :	VIP lift side door access divice beep sound issue resolved power supply change but Power under observation 2- 3 day																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	VIP lift side door access divice beep sound issue resolved power supply change but Power under observation 2- 3 day																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-02-2023 11:04:51</td><td>Ravi Rajbhar</td><td>Completed</td><td>VIP lift side door access divice beep sound issue resolved power supply change but Power under observation 2- 3 day</td><td></td></tr><tr><td>14-02-2023 10:07:50</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-02-2023 11:04:51	Ravi Rajbhar	Completed	VIP lift side door access divice beep sound issue resolved power supply change but Power under observation 2- 3 day		14-02-2023 10:07:50	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
14-02-2023 11:04:51	Ravi Rajbhar	Completed	VIP lift side door access divice beep sound issue resolved power supply change but Power under observation 2- 3 day																	
14-02-2023 10:07:50	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>21-03-2023 02:27:47</td><td>Shiva Meena</td><td>Camera fitting done and DC and bnc cheng done Wark complete</td></tr><tr><td>18-03-2023 03:29:58</td><td>Ravi Rajbhar</td><td>VIP lift side new access control divice install with emlock connected or exit switch all ok working done and old divice hondover to rajendra maintenance parson total 5 card add to divice 3 card admin access or two card only access and one parson finger add</td></tr></tbody></table>					Date Time	Technician Name	Remark	21-03-2023 02:27:47	Shiva Meena	Camera fitting done and DC and bnc cheng done Wark complete	18-03-2023 03:29:58	Ravi Rajbhar	VIP lift side new access control divice install with emlock connected or exit switch all ok working done and old divice hondover to rajendra maintenance parson total 5 card add to divice 3 card admin access or two card only access and one parson finger add						
Date Time	Technician Name	Remark																		
21-03-2023 02:27:47	Shiva Meena	Camera fitting done and DC and bnc cheng done Wark complete																		
18-03-2023 03:29:58	Ravi Rajbhar	VIP lift side new access control divice install with emlock connected or exit switch all ok working done and old divice hondover to rajendra maintenance parson total 5 card add to divice 3 card admin access or two card only access and one parson finger add																		