

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12831																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9619907222																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	28-09-2024 12:23:21																						
Vendor Details :																									
Company Name/Client Name :	Mitul Shah	Customer's Mobile :	9619907222	Name :	Chirag Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	in mobile and tv cameras offline issue - 6352717328																								
Technician Comment :	There is issue in electric bord socket so swap and used another plug point now working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	There is issue in electric bord socket so swap and used another plug point now working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-10-2024 01:36:01</td><td>Atique Salmani</td><td>Completed</td><td>There is issue in electric bord socket so swap and used another plug point now working ok.</td><td></td></tr><tr><td>01-10-2024 11:30:21</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>28-09-2024 02:47:05</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-10-2024 01:36:01	Atique Salmani	Completed	There is issue in electric bord socket so swap and used another plug point now working ok.		01-10-2024 11:30:21	Atique Salmani	New		-	28-09-2024 02:47:05	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
01-10-2024 01:36:01	Atique Salmani	Completed	There is issue in electric bord socket so swap and used another plug point now working ok.																						
01-10-2024 11:30:21	Atique Salmani	New		-																					
28-09-2024 02:47:05	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-04-2023 03:01:36</td><td>YogeshDesai</td><td></td></tr><tr><td>12-04-2023 02:06:11</td><td>Shiva Meena</td><td>4 nuw camera installed done and nvr installed done Wark complete handover done</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-04-2023 03:01:36	YogeshDesai		12-04-2023 02:06:11	Shiva Meena	4 nuw camera installed done and nvr installed done Wark complete handover done											
Date Time	Technician Name	Remark																							
15-04-2023 03:01:36	YogeshDesai																								
12-04-2023 02:06:11	Shiva Meena	4 nuw camera installed done and nvr installed done Wark complete handover done																							