

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13873															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9810080819														
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153											
Ticket Type :	Call Basis	Date & Time :	20-01-2025 03:37:10												
Vendor Details :															
Company Name/Client Name :	Neil J Control	Customer's Mobile :	9810080819	Name :	Dabral Sir										
Address :															
Mumbai , , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	Lalit hotel - 1 IP and 4 analog cameras adapter to be changed.														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :	Lalit hotel - 1 IP and 4 analog cameras adapter changed complaint solved														
Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>21-01-2025 02:34:49</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></table>					Date Time	Technician Name	Status	Remark	Sign	21-01-2025 02:34:49	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign											
21-01-2025 02:34:49	PravinJagade	New		-											
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>28-12-2024 12:29:04</td><td>ChandanYadav</td><td>1)one parking area camera new bike parking camera issue solved 2)One camera near lobby angle setting done 3)camera in 1st floor dome camera issue resolved 4)service camera issue solved power supply issue 5)one ip camera near spa dome camera issue pending power issue solved 6)camera in Under UB floor bullet camera issue solved 7)One dome camera issue solved 8)Main gate cabin camera issue resolved</td></tr><tr><td>06-12-2024 12:02:52</td><td>Sonu Kumar</td><td>2 analog dome camera install working ok and 4 chanal dahua dvr install and 1 tb hard disk install and main gate old dvr install and hard disk install</td></tr></table>					Date Time	Technician Name	Remark	28-12-2024 12:29:04	ChandanYadav	1)one parking area camera new bike parking camera issue solved 2)One camera near lobby angle setting done 3)camera in 1st floor dome camera issue resolved 4)service camera issue solved power supply issue 5)one ip camera near spa dome camera issue pending power issue solved 6)camera in Under UB floor bullet camera issue solved 7)One dome camera issue solved 8)Main gate cabin camera issue resolved	06-12-2024 12:02:52	Sonu Kumar	2 analog dome camera install working ok and 4 chanal dahua dvr install and 1 tb hard disk install and main gate old dvr install and hard disk install	
Date Time	Technician Name	Remark													
28-12-2024 12:29:04	ChandanYadav	1)one parking area camera new bike parking camera issue solved 2)One camera near lobby angle setting done 3)camera in 1st floor dome camera issue resolved 4)service camera issue solved power supply issue 5)one ip camera near spa dome camera issue pending power issue solved 6)camera in Under UB floor bullet camera issue solved 7)One dome camera issue solved 8)Main gate cabin camera issue resolved													
06-12-2024 12:02:52	Sonu Kumar	2 analog dome camera install working ok and 4 chanal dahua dvr install and 1 tb hard disk install and main gate old dvr install and hard disk install													