Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE8690								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob.	9810080819							
Technician Name	Shiva Meena			Technician Mobil	e 748956	7489567735		
Ticket Type :	Complain	Date & Time :		28-06-2023 11:00:51				
Vendor Details :								
Company Name/Client Name :	Neil J Control	Customer's Mobile :		9810080819	Name :	Name: Dab		
Address:								
Mumbai , , , , Maharashtra								
AMC Details :								
Expiry Date :	01-01-1970 05:3	0:00		Type:				
Product Name:	CCTV							
Complain :	Main gate parking 4 camera off issue							
Technician Comment :								
Complain Operator :	Desktop - Apurva Vajaria							
Remark:								
Status History:	Date Time		Technician Name		Status	Remark	Sign	
	30-06-2023 11:05:12		Shiva I	Meena	New		-	
	28-06-2023 11:01:02		Shiva Meena N		New	ew -		
Previous Complain History	Date Time	Technician Name	Remark					
•	20-07-2023 01:17:17	Sonu Kumar	Total 4 camera off issue resolved working ok 1 reaception lobby and s pool and bike parking and flag post $\ensuremath{\mathrm{mp}}$					
	08-06-2023 10:44:48	Atique Salmani	but sam in rj 6 s piece . (working reommy camera check o phase c majesti camera resolve was ren	(1)Sys corridor cameras linse waves issue checked and cahned BNC but same issue also check on vedeo baloon same issue becz cable joint in rj 6 so it's as it's . If need to clear cable need to changed in 1 single piece . (2) 7th floor701 /702 near . new camera changed set angel working ok. (3) engeneering office also camera faulty so which one reommved from 7 floor installed in enenaring office. (4) Reception 2 ip camera shifting plus angel settings done . (5.) Lounge camera also check old camera reinstalled (6) majestic back area corridor reverse phase coming so adaptor not working resolved issue working ok (7) majestic back area camera faulty ohms power ok. (8) apartment 2 camera issue resolved there is SMPS was disconnected so chek n resolve working ok. (9) baloochi back side corridor ip camera cable was remooved from Poe switch so check the cable and connect in Poe switch working ok.				