

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15476															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	7738060557														
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949											
Ticket Type :	Complain	Date & Time :	04-08-2025 10:55:06												
Vendor Details :															
Company Name/Client Name :	Buddha Chs - Mahavir Aquila	Customer's Mobile :	7738060557	Name :	Damji Shamji										
Address :															
Mumbai , , , 400077 , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	5-6 cameras off issue need to check														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>04-08-2025 10:55:15</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></table>					Date Time	Technician Name	Status	Remark	Sign	04-08-2025 10:55:15	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign											
04-08-2025 10:55:15	Rahul Mhapralkar	New		-											
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>12-08-2025 10:55:36</td><td>Rahul Mhapralkar</td><td></td></tr><tr><td>06-08-2025 11:06:48</td><td>Rahul Mhapralkar</td><td>New USB extender installed now working normally.</td></tr></table>					Date Time	Technician Name	Remark	12-08-2025 10:55:36	Rahul Mhapralkar		06-08-2025 11:06:48	Rahul Mhapralkar	New USB extender installed now working normally.	
Date Time	Technician Name	Remark													
12-08-2025 10:55:36	Rahul Mhapralkar														
06-08-2025 11:06:48	Rahul Mhapralkar	New USB extender installed now working normally.													