## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE5486 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9869913157 **No. : Technician Name** Atique Salmani **Technician Mobile** 8080922984 Complain 18-05-2022 09:50:32 **Ticket Type :** Date & Time : **Vendor Details :** St Anthony Customer's Mobile 9869913157 Company Name : Darryll Name/Client Name School Gomes Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Ppm **Complain**: cctv ppm done and one SMPS changed all cameras working ok . Technician **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : ppm done and one SMPS changed all cameras working ok . **Status History : Technician Name Date Time** Status Remark Sign 19-05-2022 10:21:34 Atique Salmani Completed ppm done and one SMPS changed all cameras working ok. Atique Salmani 19-05-2022 09:51:21 New 18-05-2022 09:50:54 Atique Salmani New 18-05-2022 09:50:32 Atique Salmani New **Previous** Technician **Date Time** Remark **Complain History** Name : 05-04-2022 Atique Salmani there is 2 dvr 1 is hikvision and second is cp plus and in tv 2 port 09:23:02 2 port is ok 1st port faulty so its painding . 17-03-2022 Neeraj grunnd aira 3 camera video disturbing issue solved and assembly 10:07:35 Chauhan hool camera disturbens not clear cabling issue and first floor camera issue solve and class room 6 camera issue solve and grunnd aira 1 camera cable issue and main gate camera starting and ending MTR recheck and 3 camera angle setting and all camera working okk. required New camera staircase aira and confirm to school manesment.