## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE8620 **Priority** : Low **Created By :** Admin - Apurva Vajaria Complaint 7738444305 Mob. No. : Technician Sonu Kumar **Technician Mobile** 8454016444 Name : Complain Date & Time : 21-06-2023 10:19:36 **Ticket Type : Vendor Details :** Customer's Mobile **Rahul International** 7738444305 Darshan Sir Company Name : Name/Client - Mira Road Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name** CCTV class no. 803 and 808 cable need to change and 8-10 cameras off issue **Complain**: Technician 803-808 camera cabling Done and 803 camera install and 808 camera install pending and terrace lift side camera collect for reapering purpose camera off 8th floor all camera working ok and 7th Comment · floor all camera working ok and 1 camera off staircase side camera collect for reapering purpose and 6th floor all camer working ok and 1 camera off lift passage camera collect for reapering purpose and 5th floor all camera working ok and 4th floor all camera working ok Complain Desktop - Apurva Vajaria **Operator** : 803-808 camera cabling Done and 803 camera install and 808 camera install pending and terrace **Remark** : lift side camera collect for reapering purpose camera off 8th floor all camera working ok and 7th floor all camera working ok and 1 camera off staircase side camera collect for reapering purpose and 6th floor all camer working ok and 1 camera off lift passage camera collect for reapering purpose and 5th floor all camera working ok and 4th floor all camera working ok

Status History :	Date Time	Technician Name	Status	Remark	Sign
	23-06-2023 04:37:58	Sonu Kumar	Completed	803-808 camera cabling Done and 803 camera install and 808 camera install pending and terrace lift side camera collect for reapering purpose camera off 8th floor all camera working ok and 7th floor all camera working ok and 1 camera off staircase side camera collect for reapering purpose and 6th floor all camer working ok and 1 camera off lift passage camera collect for reapering purpose and 5th floor all camera working ok and 4th floor all camera working ok	WY.
	23-06-2023 10:00:02	Sonu Kumar	New		-
	22-06-2023 11:09:33	Sonu Kumar	New		-
	21-06-2023 10:34:14	Sonu Kumar	New		-
	21-06-2023 10:19:46	Sonu Kumar	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	17-07-2023 11:27:16	Sonu Kumar	5th floor studio room 2 and 6th floor lift passage camera off issue resolved working ok		
	14-07-2023 03:57:33	Sonu Kumar	Ris Mira road 1 8th floor class room 808 and terrace lift side camera installed 2 7th floor stair case side camera installed 3 6th floor lift passage camera installed 4 5th floor staircase 2 side camera installed 5 3rd floor dvr recording issue resolved and 4 camera angle settings done 6 4th floor all camera working ok and 409 out side camera pending camera reapering		