




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8977																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7738444305																			
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																
Ticket Type :	Complain	Date & Time :	26-07-2023 10:15:38																	
Vendor Details :																				
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7738444305	Name :	Darshan Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	1st floor 1 camera not viewing clear 4th floor 409 repaired camera need to install 4th , 5th , 6th , 7th or 8th floor some cameras recording not saved "																			
Technician Comment :	4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-07-2023 04:57:05</td><td>Sonu Kumar</td><td>Completed</td><td>4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok</td><td></td></tr><tr><td>26-07-2023 10:15:48</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-07-2023 04:57:05	Sonu Kumar	Completed	4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok		26-07-2023 10:15:48	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																
26-07-2023 04:57:05	Sonu Kumar	Completed	4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok																	
26-07-2023 10:15:48	Sonu Kumar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-09-2023 01:04:39</td><td>PravinJagade</td><td></td></tr><tr><td>24-08-2023 11:35:50</td><td>Sonu Kumar</td><td>Back side dvr offline issue resolved working ok and 6th floor and 7th floor camera chaking pending and ground floor dvr adupter change</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-09-2023 01:04:39	PravinJagade		24-08-2023 11:35:50	Sonu Kumar	Back side dvr offline issue resolved working ok and 6th floor and 7th floor camera chaking pending and ground floor dvr adupter change						
Date Time	Technician Name	Remark																		
01-09-2023 01:04:39	PravinJagade																			
24-08-2023 11:35:50	Sonu Kumar	Back side dvr offline issue resolved working ok and 6th floor and 7th floor camera chaking pending and ground floor dvr adupter change																		