Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details: VE9111							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	7738444305						
Technician Name :	Pravin Jagade		Tecl	nnician Mobile	7262044153		
Ticket Type:	Complain Date & Time :		e: 09-0	-08-2023 11:10:59			
Vendor Details :							
Company Name/Client Name :	Rahul Internationa - Mira Road	Customer's M	Mobile 773	8444305	Name :	Darshan Sir	
Address:							
Mumbai , , , , Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Туре) :			
Product Name:	CCTV						
Complain:	Main entrance gate no 4 Main entrance gate no 5 Main entrance gate no 3 Football ground Vollyball ground Counselor office 7th floor common room 8th room 805,809 Angle set need Main entrance get no 5 out side Ground floor counselor room offline						
Technician Comment :	1. Gate no $3_4_5_$ and foot baal and bolly ball area camera offline issue resolved working ok 2. 7th floor boy common room camera faulty collect from reapering. 3. Counseling room no video issue resolve ok 4. 805 angle setting done. 5. Sum camera need for naming 6. Main Reception 4 camera install but 2 camera viewing found and 2 camera not viewing not found						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	1. Gate no 3_4_5_ and foot baal and bolly ball area camera offline issue resolved working ok 2. 7th floor boy common room camera faulty collect from reapering. 3. Counseling room no video issue resolve ok 4. 805 angle setting done. 5. Sum camera need for naming 6. Main Reception 4 camera install but 2 camera viewing found and 2 camera not viewing not found						
Status History	Date Time	Technician Name	Status	Re	mark	Sign	
•	11-08-2023 02:00:26	PravinJagade	Completed	bolly ball area car resolved working common room car from reapering. 3 no video issue res setting done. 5. S' naming 6. Main R install but 2 came	ok 2. 7th floor boy mera faulty collect .Counseling room olve ok 4. 805 ang um camera need fo eception 4 camera	le or	
	11-08-2023 11:49:16	PravinJagade	New			-	
	09-08-2023 11:11:06	PravinJagade	New			-	

Previous
Complain
History :

Date Time	Technician Name	Remark
01-09-2023 01:04:39	PravinJagade	
24-08-2023 11:35:50	Sonu Kumar	Back side dvr offline issue resolved working ok and 6th floor and 7th floor camera chaking pending and ground floor dvr adupter change