Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

| Service Status D | etails : VE2288 | | | | | | | | |
|----------------------------------|---|---------------------|---------------------|------------|------------|--|--|--|--|
| Priority: | High | | | | | | | | |
| Created By: | Admin - Apurva Vajaria | | | | | | | | |
| Complaint Mob. No. : | 9920234005 | | | | | | | | |
| Technician Name : | Yasin Shaikh | | Technician Mobile : | 8689802313 | | | | | |
| Ticket Type : | Complain | Date & Time : | 25-11-2020 12:16:47 | | | | | | |
| Vendor Details : | | | | | | | | | |
| Company Name/Client Name : | Ashford Royale | Customer's Mobile : | 9920234005 | Name: | Deepak Sir | | | | |
| Address: | | | | | | | | | |
| Mumbai,,,400078, Maharashtra | | | | | | | | | |
| AMC Details : | _ | | _ | _ | | | | | |
| Expiry Date : | 01-01-1970 05:30:00 | | Type: | | | | | | |
| Product Name : | VDP | | | | | | | | |
| Complain: | install vdp repaired and also camera issue | | | | | | | | |
| Technician Comment : | 01 camera power cable issue by reconnection working ok and 04 camera disturbance issue by camera side and DVR site reconnection but underobservation ok all camera working ok | | | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | | | |
| Remark: | 01 camera power cable issue by reconnection working ok and 04 camera disturbance issue by camera side and DVR site reconnection but underobservation ok all camera working ok | | | | | | | | |

| Status History : | Date Time | Technician Name | Status | Remark | Sign |
|-----------------------------------|----------------------------------|-----------------|--------------|---|------|
| | 05-12-2020 04:22:04 | YasinShaikh | Completed | 01 camera power cable issue by reconnection working ok and 04 camera disturbance issue by camera side and DVR site reconnection but underobservation ok all camera working ok | DW) |
| | 03-12-2020 10:29:52 | YasinShaikh | New | | - |
| | 01-12-2020 09:53:37 | YasinShaikh | New | | - |
| | 30-11-2020 11:03:07 | YasinShaikh | New | | - |
| | 26-11-2020 07:40:21 | YasinShaikh | Work Pending | b wing door phone installation done Main gate new camera installation done and p1 camera re-installing done and power supply week cameras plutcuwet | |
| | 25-11-2020 12:17:00 | YasinShaikh | New | | - |
| | 25-11-2020 12:16:47 | YasinShaikh | New | | - |
| Previous Complain History : | Date Time Technician Name Remark | | | | |
| | 31-07-2023 12:52:32 | Ravi Rajbhar | | кешагк | |
| 1113t01y . | 31-03-2023 10:37:16 | Ravi Rajbhar | | b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat | |